



## TEMPLATE - Troubled Cube Calls

Description	Calls containing Internal Error Codes (IEC)
Date/Time Range	Oct 10, 2021 12:00:00 AM CDT - Oct 18, 2021 11:59:00 PM CDT
Cluster	Cisco CUBE

### Search Criteria Summary

Search Set	Total Call Count
Total Trouble Calls	116

### Internal Error Code Summary

Internal Error Code	Total Call Count
<u>1.1.129.7.68.0</u>	<u>60</u>
<u>1.1.278.7.109.0</u>	<u>23</u>
<u>1.1.128.11.5.0</u>	<u>14</u>
<u>1.1.129.7.66.0</u>	<u>13</u>



Internal Error Code	Total Call Count
<u>1.1.129.7.67.0</u>	<u>2</u>
<u>1.1.185.7.8.0</u>	<u>2</u>
<u>1.1.186.7.7.5</u>	<u>1</u>
<u>1.1.96.7.25.0</u>	<u>1</u>
<b>TOTALS</b>	<b>116</b>



## Internal Error Code Call Details

Internal Error Code: 1.1.129.7.68.0

Total Call Count: 60

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 15, 2021 10:45:59 AM CDT	Oct 15, 2021 10:46:59 AM CDT	Oct 15, 2021 10:46:59 AM CDT	Answer	2515101234	2519371234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 10:45:59 AM CDT	Oct 15, 2021 10:46:59 AM CDT	Oct 15, 2021 10:46:59 AM CDT	Originate	+12515101234	2519371234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 15, 2021 2:35:37 PM CDT	Oct 15, 2021 2:36:37 PM CDT	Oct 15, 2021 2:36:37 PM CDT	Answer	6128451234	9524961234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 2:35:37 PM CDT	Oct 15, 2021 2:36:37 PM CDT	Oct 15, 2021 2:36:37 PM CDT	Originate	+16128451234	9524961234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 15, 2021 2:51:05 PM CDT	Oct 15, 2021 2:52:05 PM CDT	Oct 15, 2021 2:52:05 PM CDT	Answer	3347901234	3343611234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 2:51:05 PM CDT	Oct 15, 2021 2:52:05 PM CDT	Oct 15, 2021 2:52:05 PM CDT	Originate	+13347901234	3343611234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 15, 2021 4:42:02 PM CDT	Oct 15, 2021 4:43:02 PM CDT	Oct 15, 2021 4:43:02 PM CDT	Answer	+15185851234	+15185851234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 4:42:02 PM CDT	Oct 15, 2021 4:43:02 PM CDT	Oct 15, 2021 4:43:02 PM CDT	Originate	5185851234	5185851234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 15, 2021 5:06:07 PM CDT	Oct 15, 2021 5:07:07 PM CDT	Oct 15, 2021 5:07:07 PM CDT	Answer	+19166861234	+12092001234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 5:06:07 PM CDT	Oct 15, 2021 5:07:07 PM CDT	Oct 15, 2021 5:07:07 PM CDT	Originate	9166861234	2092001234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 15, 2021 6:43:33 PM CDT	Oct 15, 2021 6:44:33 PM CDT	Oct 15, 2021 6:44:33 PM CDT	Answer	+13344181234	+13344181234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 6:43:33 PM CDT	Oct 15, 2021 6:44:33 PM CDT	Oct 15, 2021 6:44:33 PM CDT	Originate	3344181234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 15, 2021 6:46:05 PM CDT	Oct 15, 2021 6:47:05 PM CDT	Oct 15, 2021 6:47:05 PM CDT	Answer	+13344181234	+13344181234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 15, 2021 6:46:05 PM CDT	Oct 15, 2021 6:47:05 PM CDT	Oct 15, 2021 6:47:05 PM CDT	Originate	3344181234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 16, 2021 5:05:00 PM CDT	Oct 16, 2021 5:06:00 PM CDT	Oct 16, 2021 5:06:00 PM CDT	Answer	+13344181234	+13345261234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 16, 2021 5:05:00 PM CDT	Oct 16, 2021 5:06:00 PM CDT	Oct 16, 2021 5:06:00 PM CDT	Originate	3344181234	3345261234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 16, 2021 5:45:47 PM CDT	Oct 16, 2021 5:46:47 PM CDT	Oct 16, 2021 5:46:47 PM CDT	Answer	+13344181234	+13344181234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 16, 2021 5:45:47 PM CDT	Oct 16, 2021 5:46:47 PM CDT	Oct 16, 2021 5:46:47 PM CDT	Originate	3344181234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 16, 2021 8:57:02 PM CDT	Oct 16, 2021 8:58:02 PM CDT	Oct 16, 2021 8:58:02 PM CDT	Answer	+13344181234	+13343121234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 16, 2021 8:57:02 PM CDT	Oct 16, 2021 8:58:02 PM CDT	Oct 16, 2021 8:58:02 PM CDT	Originate	3344181234	3343121234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 16, 2021 11:59:21 PM CDT	Oct 17, 2021 12:00:21 AM CDT	Oct 17, 2021 12:00:21 AM CDT	Answer	+18435451234	+18432641234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 16, 2021 11:59:21 PM CDT	Oct 17, 2021 12:00:21 AM CDT	Oct 17, 2021 12:00:21 AM CDT	Originate	8435451234	8432641234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 6:48:41 AM CDT	Oct 17, 2021 6:49:41 AM CDT	Oct 17, 2021 6:49:41 AM CDT	Answer	+18435451234	+18435461234	00:00:00	Two-Way Call		No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 6:48:41 AM CDT	Oct 17, 2021 6:49:41 AM CDT	Oct 17, 2021 6:49:41 AM CDT	Originate	8435451234	8435461234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 8:21:59 AM CDT	Oct 17, 2021 8:22:59 AM CDT	Oct 17, 2021 8:22:59 AM CDT	Originate	9374561234	5132261234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 8:21:59 AM CDT	Oct 17, 2021 8:23:00 AM CDT	Oct 17, 2021 8:23:00 AM CDT	Answer	+19374561234	+15132261234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 8:51:03 AM CDT	Oct 17, 2021 8:52:03 AM CDT	Oct 17, 2021 8:52:03 AM CDT	Answer	+14097461234	+14097461234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 8:51:03 AM CDT	Oct 17, 2021 8:52:03 AM CDT	Oct 17, 2021 8:52:03 AM CDT	Originate	4097461234	4097461234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 9:02:42 AM CDT	Oct 17, 2021 9:03:42 AM CDT	Oct 17, 2021 9:03:42 AM CDT	Answer	+13344181234	+13348741234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 9:02:42 AM CDT	Oct 17, 2021 9:03:42 AM CDT	Oct 17, 2021 9:03:42 AM CDT	Originate	3344181234	3348741234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 10:06:09 AM CDT	Oct 17, 2021 10:07:09 AM CDT	Oct 17, 2021 10:07:09 AM CDT	Answer	+17087281234	+13122821234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 10:06:09 AM CDT	Oct 17, 2021 10:07:09 AM CDT	Oct 17, 2021 10:07:09 AM CDT	Originate	7087281234	3122821234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 10:47:17 AM CDT	Oct 17, 2021 10:48:17 AM CDT	Oct 17, 2021 10:48:17 AM CDT	Answer	4085331234	3188711234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 10:47:17 AM CDT	Oct 17, 2021 10:48:17 AM CDT	Oct 17, 2021 10:48:17 AM CDT	Originate	+14085331234	3188711234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 10:50:54 AM CDT	Oct 17, 2021 10:51:54 AM CDT	Oct 17, 2021 10:51:54 AM CDT	Answer	3462871234	3343611234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 10:50:54 AM CDT	Oct 17, 2021 10:51:54 AM CDT	Oct 17, 2021 10:51:54 AM CDT	Originate	+13462871234	3343611234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 12:00:41 PM CDT	Oct 17, 2021 12:01:41 PM CDT	Oct 17, 2021 12:01:41 PM CDT	Answer	+13107611234	+18005201234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 12:00:41 PM CDT	Oct 17, 2021 12:01:41 PM CDT	Oct 17, 2021 12:01:41 PM CDT	Originate	3107611234	8005201234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 1:16:23 PM CDT	Oct 17, 2021 1:17:23 PM CDT	Oct 17, 2021 1:17:23 PM CDT	Answer	+16016311234	+16016381234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 1:16:23 PM CDT	Oct 17, 2021 1:17:23 PM CDT	Oct 17, 2021 1:17:23 PM CDT	Originate	6016311234	6016381234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 1:35:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Answer	+17145021234	+16573251234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 1:35:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Originate	7145021234	6573251234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 1:35:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Answer	7145021234	6573251234	00:00:00	Two-Way Call		Normal call clearing
Oct 17, 2021 1:35:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Oct 17, 2021 1:36:32 PM CDT	Originate	+17145021234	6573251234	00:00:00	Two-Way Call		Normal call clearing
Oct 17, 2021 2:02:51 PM CDT	Oct 17, 2021 2:03:52 PM CDT	Oct 17, 2021 2:03:52 PM CDT	Answer	+19725221234	+19726411234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 2:02:51 PM CDT	Oct 17, 2021 2:03:52 PM CDT	Oct 17, 2021 2:03:52 PM CDT	Originate	9725221234	9726411234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 2:10:28 PM CDT	Oct 17, 2021 2:11:28 PM CDT	Oct 17, 2021 2:11:28 PM CDT	Answer	+19725121234	+12143421234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 2:10:28 PM CDT	Oct 17, 2021 2:11:28 PM CDT	Oct 17, 2021 2:11:28 PM CDT	Originate	9725121234	2143421234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 2:46:54 PM CDT	Oct 17, 2021 2:47:55 PM CDT	Oct 17, 2021 2:47:55 PM CDT	Originate	8033531234	8037471234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 2:46:55 PM CDT	Oct 17, 2021 2:47:55 PM CDT	Oct 17, 2021 2:47:55 PM CDT	Answer	+18033531234	+18037471234	00:00:00	Two-Way Call		No answer from user (user alerted)





H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 2:50:08 PM CDT	Oct 17, 2021 2:51:08 PM CDT	Oct 17, 2021 2:51:08 PM CDT	Answer	+12519371234	+12519371234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 2:50:08 PM CDT	Oct 17, 2021 2:51:08 PM CDT	Oct 17, 2021 2:51:08 PM CDT	Originate	2519371234	2519371234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 2:52:44 PM CDT	Oct 17, 2021 2:53:44 PM CDT	Oct 17, 2021 2:53:44 PM CDT	Answer	+19725221234	+14696441234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 2:52:44 PM CDT	Oct 17, 2021 2:53:44 PM CDT	Oct 17, 2021 2:53:44 PM CDT	Originate	9725221234	4696441234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 2:57:29 PM CDT	Oct 17, 2021 2:58:29 PM CDT	Oct 17, 2021 2:58:29 PM CDT	Answer	+18033531234	+18153891234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 2:57:29 PM CDT	Oct 17, 2021 2:58:29 PM CDT	Oct 17, 2021 2:58:29 PM CDT	Originate	8033531234	8153891234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 3:36:20 PM CDT	Oct 17, 2021 3:37:20 PM CDT	Oct 17, 2021 3:37:20 PM CDT	Answer	+13344181234	+13343751234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 3:36:20 PM CDT	Oct 17, 2021 3:37:20 PM CDT	Oct 17, 2021 3:37:20 PM CDT	Originate	3344181234	3343751234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 5:30:25 PM CDT	Oct 17, 2021 5:31:25 PM CDT	Oct 17, 2021 5:31:25 PM CDT	Answer	+13188721234	+13186581234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 5:30:25 PM CDT	Oct 17, 2021 5:31:25 PM CDT	Oct 17, 2021 5:31:25 PM CDT	Originate	3188721234	3186581234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 5:31:25 PM CDT	Oct 17, 2021 5:32:25 PM CDT	Oct 17, 2021 5:32:25 PM CDT	Answer	+13188721234	+13186581234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 5:31:25 PM CDT	Oct 17, 2021 5:32:25 PM CDT	Oct 17, 2021 5:32:25 PM CDT	Originate	3188721234	3186581234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 6:17:22 PM CDT	Oct 17, 2021 6:18:23 PM CDT	Oct 17, 2021 6:18:23 PM CDT	Answer	+13188721234	+13186581234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 6:17:22 PM CDT	Oct 17, 2021 6:18:23 PM CDT	Oct 17, 2021 6:18:23 PM CDT	Originate	3188721234	3186581234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 11:23:47 PM CDT	Oct 17, 2021 11:24:47 PM CDT	Oct 17, 2021 11:24:47 PM CDT	Answer	+15033501234	+15035761234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 17, 2021 11:23:47 PM CDT	Oct 17, 2021 11:24:47 PM CDT	Oct 17, 2021 11:24:47 PM CDT	Originate	5033501234	5035761234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 17, 2021 11:25:14 PM CDT	Oct 17, 2021 11:26:14 PM CDT	Oct 17, 2021 11:26:14 PM CDT	Answer	+18033531234	+19085021234	00:00:00	Two-Way Call		No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 11:25:14 PM CDT	Oct 17, 2021 11:26:14 PM CDT	Oct 17, 2021 11:26:14 PM CDT	Originate	8033531234	9085021234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 7:23:40 AM CDT	Oct 18, 2021 7:24:41 AM CDT	Oct 18, 2021 7:24:41 AM CDT	Answer	+13344181234	+13343651234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 7:23:41 AM CDT	Oct 18, 2021 7:24:41 AM CDT	Oct 18, 2021 7:24:41 AM CDT	Originate	3344181234	3343651234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 7:59:09 AM CDT	Oct 18, 2021 8:00:09 AM CDT	Oct 18, 2021 8:00:09 AM CDT	Answer	+16016311234	+16016361234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 7:59:09 AM CDT	Oct 18, 2021 8:00:09 AM CDT	Oct 18, 2021 8:00:09 AM CDT	Originate	6016311234	6016361234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 8:34:09 AM CDT	Oct 18, 2021 8:35:09 AM CDT	Oct 18, 2021 8:35:09 AM CDT	Answer	+13188721234	+18448371234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 8:34:09 AM CDT	Oct 18, 2021 8:35:09 AM CDT	Oct 18, 2021 8:35:09 AM CDT	Originate	3188721234	8448371234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 9:04:31 AM CDT	Oct 18, 2021 9:05:31 AM CDT	Oct 18, 2021 9:05:31 AM CDT	Answer	+13344181234	+13348741234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 9:04:31 AM CDT	Oct 18, 2021 9:05:31 AM CDT	Oct 18, 2021 9:05:31 AM CDT	Originate	3344181234	3348741234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 9:15:33 AM CDT	Oct 18, 2021 9:16:33 AM CDT	Oct 18, 2021 9:16:33 AM CDT	Answer	+19726411234	+19727081234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 9:15:33 AM CDT	Oct 18, 2021 9:16:33 AM CDT	Oct 18, 2021 9:16:33 AM CDT	Originate	9726411234	9727081234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 9:52:09 AM CDT	Oct 18, 2021 9:53:08 AM CDT	Oct 18, 2021 9:53:08 AM CDT	Originate	3343611234	3343651234	00:00:00	Two-Way Call		Call Rejected
Oct 18, 2021 9:52:09 AM CDT	Oct 18, 2021 9:54:09 AM CDT	Oct 18, 2021 9:54:09 AM CDT	Answer	+13343611234	+13343651234	00:00:00	Two-Way Call		Call Rejected
Oct 18, 2021 9:53:08 AM CDT	Oct 18, 2021 9:54:09 AM CDT	Oct 18, 2021 9:54:09 AM CDT	Originate	3343611234	3343651234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 10:07:25 AM CDT	Oct 18, 2021 10:08:25 AM CDT	Oct 18, 2021 10:08:25 AM CDT	Answer	+13302021234	+13306011234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 10:07:25 AM CDT	Oct 18, 2021 10:08:25 AM CDT	Oct 18, 2021 10:08:25 AM CDT	Originate	3302021234	3306011234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 10:31:07 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Answer	+12608681234	+12604071234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 10:31:07 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Originate	2608681234	2604071234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 10:42:19 AM CDT	Oct 18, 2021 10:43:19 AM CDT	Oct 18, 2021 10:43:19 AM CDT	Answer	3344191234	3344181234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 10:42:19 AM CDT	Oct 18, 2021 10:43:19 AM CDT	Oct 18, 2021 10:43:19 AM CDT	Originate	+13344191234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 10:44:30 AM CDT	Oct 18, 2021 10:45:30 AM CDT	Oct 18, 2021 10:45:30 AM CDT	Answer	6608861234	8169221234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 10:44:30 AM CDT	Oct 18, 2021 10:45:30 AM CDT	Oct 18, 2021 10:45:30 AM CDT	Originate	+16608861234	8169221234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 11:34:05 AM CDT	Oct 18, 2021 11:35:05 AM CDT	Oct 18, 2021 11:35:05 AM CDT	Answer	+13344181234	+13347471234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 11:34:05 AM CDT	Oct 18, 2021 11:35:05 AM CDT	Oct 18, 2021 11:35:05 AM CDT	Originate	3344181234	3347471234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 11:35:53 AM CDT	Oct 18, 2021 11:36:53 AM CDT	Oct 18, 2021 11:36:53 AM CDT	Answer	8039201234	8033531234	00:00:00	Two-Way Call		Normal call clearing
Oct 18, 2021 11:35:53 AM CDT	Oct 18, 2021 11:36:53 AM CDT	Oct 18, 2021 11:36:53 AM CDT	Originate	+18039201234	8033531234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 11:57:58 AM CDT	Oct 18, 2021 11:58:59 AM CDT	Oct 18, 2021 11:58:59 AM CDT	Answer	+15033501234	+12095771234	00:00:00	Two-Way Call		No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 11:57:58 AM CDT	Oct 18, 2021 11:58:59 AM CDT	Oct 18, 2021 11:58:59 AM CDT	Originate	5033501234	2095771234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 12:05:23 PM CDT	Oct 18, 2021 12:06:23 PM CDT	Oct 18, 2021 12:06:23 PM CDT	Answer	+17704931234	+14044591234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 12:05:23 PM CDT	Oct 18, 2021 12:06:23 PM CDT	Oct 18, 2021 12:06:23 PM CDT	Originate	7704931234	4044591234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 12:40:18 PM CDT	Oct 18, 2021 12:41:18 PM CDT	Oct 18, 2021 12:41:18 PM CDT	Answer	+16016311234	+16014461234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 12:40:18 PM CDT	Oct 18, 2021 12:41:18 PM CDT	Oct 18, 2021 12:41:18 PM CDT	Originate	6016311234	6014461234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 2:11:31 PM CDT	Oct 18, 2021 2:12:31 PM CDT	Oct 18, 2021 2:12:31 PM CDT	Answer	+19122381234	+19124321234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 2:11:31 PM CDT	Oct 18, 2021 2:12:31 PM CDT	Oct 18, 2021 2:12:31 PM CDT	Originate	9122381234	9124321234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 2:14:37 PM CDT	Oct 18, 2021 2:15:37 PM CDT	Oct 18, 2021 2:15:37 PM CDT	Answer	+17325091234	+15703991234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 2:14:37 PM CDT	Oct 18, 2021 2:15:37 PM CDT	Oct 18, 2021 2:15:37 PM CDT	Originate	7325091234	5703991234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 3:18:13 PM CDT	Oct 18, 2021 3:19:13 PM CDT	Oct 18, 2021 3:19:13 PM CDT	Answer	8647231234	7063781234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 3:18:13 PM CDT	Oct 18, 2021 3:19:13 PM CDT	Oct 18, 2021 3:19:13 PM CDT	Originate	+18647231234	7063781234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 4:25:23 PM CDT	Oct 18, 2021 4:26:23 PM CDT	Oct 18, 2021 4:26:23 PM CDT	Answer	+13343611234	+13342841234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 4:25:23 PM CDT	Oct 18, 2021 4:26:23 PM CDT	Oct 18, 2021 4:26:23 PM CDT	Originate	3343611234	3342841234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 5:22:24 PM CDT	Oct 18, 2021 5:23:24 PM CDT	Oct 18, 2021 5:23:24 PM CDT	Answer	+16185091234	+16182331234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 5:22:24 PM CDT	Oct 18, 2021 5:23:24 PM CDT	Oct 18, 2021 5:23:24 PM CDT	Originate	6185091234	6182331234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 5:40:15 PM CDT	Oct 18, 2021 5:41:15 PM CDT	Oct 18, 2021 5:41:15 PM CDT	Answer	+16238721234	+16235941234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 5:40:15 PM CDT	Oct 18, 2021 5:41:15 PM CDT	Oct 18, 2021 5:41:15 PM CDT	Originate	6238721234	6235941234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 6:25:26 PM CDT	Oct 18, 2021 6:26:26 PM CDT	Oct 18, 2021 6:26:26 PM CDT	Answer	+13343611234	+13342771234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 6:25:26 PM CDT	Oct 18, 2021 6:26:26 PM CDT	Oct 18, 2021 6:26:26 PM CDT	Originate	3343611234	3342771234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 6:26:49 PM CDT	Oct 18, 2021 6:27:49 PM CDT	Oct 18, 2021 6:27:49 PM CDT	Answer	+13343611234	+13342771234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 6:26:49 PM CDT	Oct 18, 2021 6:27:49 PM CDT	Oct 18, 2021 6:27:49 PM CDT	Originate	3343611234	3342771234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 6:29:07 PM CDT	Oct 18, 2021 6:30:07 PM CDT	Oct 18, 2021 6:30:07 PM CDT	Answer	+13343611234	+13342771234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 6:29:07 PM CDT	Oct 18, 2021 6:30:07 PM CDT	Oct 18, 2021 6:30:07 PM CDT	Originate	3343611234	3342771234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 7:36:31 PM CDT	Oct 18, 2021 7:37:31 PM CDT	Oct 18, 2021 7:37:31 PM CDT	Answer	+13344181234	+13344181234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 7:36:31 PM CDT	Oct 18, 2021 7:37:31 PM CDT	Oct 18, 2021 7:37:31 PM CDT	Originate	3344181234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 7:47:17 PM CDT	Oct 18, 2021 7:48:17 PM CDT	Oct 18, 2021 7:48:17 PM CDT	Answer	+13344181234	+13344181234	00:00:00	Two-Way Call		No answer from user (user alerted)





H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 7:47:17 PM CDT	Oct 18, 2021 7:48:17 PM CDT	Oct 18, 2021 7:48:17 PM CDT	Originate	3344181234	3344181234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)
Oct 18, 2021 11:01:57 PM CDT	Oct 18, 2021 11:02:57 PM CDT	Oct 18, 2021 11:02:57 PM CDT	Answer	+14792891234	+14797631234	00:00:00	Two-Way Call		No answer from user (user alerted)
Oct 18, 2021 11:01:57 PM CDT	Oct 18, 2021 11:02:57 PM CDT	Oct 18, 2021 11:02:57 PM CDT	Originate	4792891234	4797631234	00:00:00	Two-Way Call	1.1.129.7.68.0	No answer from user (user alerted)

Internal Error Code: 1.1.278.7.109.0

Total Call Count: 23
----------------------

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 16, 2021 12:44:48 PM CDT	Oct 16, 2021 12:44:48 PM CDT	Oct 16, 2021 12:44:52 PM CDT	Answer	no_from_info	4088461234	00:00:04	Two-Way Call		Bearer capability not implemented
Oct 16, 2021 12:44:48 PM CDT	Oct 16, 2021 12:44:48 PM CDT	Oct 16, 2021 12:44:52 PM CDT	Originate	no_from_info	4088461234	00:00:04	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 16, 2021 12:46:16 PM CDT	Oct 16, 2021 12:46:16 PM CDT	Oct 16, 2021 12:46:21 PM CDT	Answer	no_from_info	4088461234	00:00:04	Two-Way Call		Bearer capability not implemented
Oct 16, 2021 12:46:16 PM CDT	Oct 16, 2021 12:46:16 PM CDT	Oct 16, 2021 12:46:21 PM CDT	Originate	no_from_info	4088461234	00:00:04	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 16, 2021 12:50:15 PM CDT	Oct 16, 2021 12:50:16 PM CDT	Oct 16, 2021 12:50:20 PM CDT	Answer	no_from_info	4088461234	00:00:04	Two-Way Call		Bearer capability not implemented
Oct 16, 2021 12:50:15 PM CDT	Oct 16, 2021 12:50:16 PM CDT	Oct 16, 2021 12:50:20 PM CDT	Originate	no_from_info	4088461234	00:00:04	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 16, 2021 12:56:16 PM CDT	Oct 16, 2021 12:56:16 PM CDT	Oct 16, 2021 12:56:21 PM CDT	Answer	no_from_info	4088461234	00:00:04	Two-Way Call		Bearer capability not implemented
Oct 16, 2021 12:56:16 PM CDT	Oct 16, 2021 12:56:16 PM CDT	Oct 16, 2021 12:56:21 PM CDT	Originate	no_from_info	4088461234	00:00:04	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 16, 2021 1:02:17 PM CDT	Oct 16, 2021 1:02:17 PM CDT	Oct 16, 2021 1:02:22 PM CDT	Answer	no_from_info	4088461234	00:00:05	Two-Way Call		Bearer capability not implemented
Oct 16, 2021 1:02:17 PM CDT	Oct 16, 2021 1:02:17 PM CDT	Oct 16, 2021 1:02:22 PM CDT	Originate	no_from_info	4088461234	00:00:04	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:24:43 AM CDT	Oct 18, 2021 1:24:59 AM CDT	Oct 18, 2021 1:25:05 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:24:43 AM CDT	Oct 18, 2021 1:24:59 AM CDT	Oct 18, 2021 1:25:05 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 1:25:12 AM CDT	Oct 18, 2021 1:25:27 AM CDT	Oct 18, 2021 1:25:33 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:25:12 AM CDT	Oct 18, 2021 1:25:27 AM CDT	Oct 18, 2021 1:25:33 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:25:16 AM CDT	Oct 18, 2021 1:25:31 AM CDT	Oct 18, 2021 1:25:37 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:25:16 AM CDT	Oct 18, 2021 1:25:31 AM CDT	Oct 18, 2021 1:25:37 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:30:37 AM CDT	Oct 18, 2021 1:30:52 AM CDT	Oct 18, 2021 1:30:59 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:30:37 AM CDT	Oct 18, 2021 1:30:52 AM CDT	Oct 18, 2021 1:30:59 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:30:59 AM CDT	Oct 18, 2021 1:31:15 AM CDT	Oct 18, 2021 1:31:21 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:30:59 AM CDT	Oct 18, 2021 1:31:15 AM CDT	Oct 18, 2021 1:31:21 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:31:32 AM CDT	Oct 18, 2021 1:31:47 AM CDT	Oct 18, 2021 1:31:54 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:31:32 AM CDT	Oct 18, 2021 1:31:47 AM CDT	Oct 18, 2021 1:31:54 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:32:05 AM CDT	Oct 18, 2021 1:32:20 AM CDT	Oct 18, 2021 1:32:27 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 1:32:05 AM CDT	Oct 18, 2021 1:32:20 AM CDT	Oct 18, 2021 1:32:27 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:32:42 AM CDT	Oct 18, 2021 1:32:57 AM CDT	Oct 18, 2021 1:33:04 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:32:42 AM CDT	Oct 18, 2021 1:32:57 AM CDT	Oct 18, 2021 1:33:04 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:32:48 AM CDT	Oct 18, 2021 1:33:04 AM CDT	Oct 18, 2021 1:33:10 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:32:48 AM CDT	Oct 18, 2021 1:33:04 AM CDT	Oct 18, 2021 1:33:10 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:33:20 AM CDT	Oct 18, 2021 1:33:36 AM CDT	Oct 18, 2021 1:33:42 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:33:20 AM CDT	Oct 18, 2021 1:33:36 AM CDT	Oct 18, 2021 1:33:42 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:34:07 AM CDT	Oct 18, 2021 1:34:23 AM CDT	Oct 18, 2021 1:34:29 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:34:07 AM CDT	Oct 18, 2021 1:34:23 AM CDT	Oct 18, 2021 1:34:29 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:34:29 AM CDT	Oct 18, 2021 1:34:44 AM CDT	Oct 18, 2021 1:34:50 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:34:29 AM CDT	Oct 18, 2021 1:34:44 AM CDT	Oct 18, 2021 1:34:51 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 1:34:39 AM CDT	Oct 18, 2021 1:34:55 AM CDT	Oct 18, 2021 1:35:01 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:34:39 AM CDT	Oct 18, 2021 1:34:55 AM CDT	Oct 18, 2021 1:35:01 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:35:12 AM CDT	Oct 18, 2021 1:35:28 AM CDT	Oct 18, 2021 1:35:34 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:35:12 AM CDT	Oct 18, 2021 1:35:28 AM CDT	Oct 18, 2021 1:35:34 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:35:37 AM CDT	Oct 18, 2021 1:35:53 AM CDT	Oct 18, 2021 1:35:59 AM CDT	Answer	5168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:35:37 AM CDT	Oct 18, 2021 1:35:53 AM CDT	Oct 18, 2021 1:35:59 AM CDT	Originate	+15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:36:01 AM CDT	Oct 18, 2021 1:36:16 AM CDT	Oct 18, 2021 1:36:23 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:36:01 AM CDT	Oct 18, 2021 1:36:16 AM CDT	Oct 18, 2021 1:36:23 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:36:33 AM CDT	Oct 18, 2021 1:36:49 AM CDT	Oct 18, 2021 1:36:55 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented
Oct 18, 2021 1:36:33 AM CDT	Oct 18, 2021 1:36:49 AM CDT	Oct 18, 2021 1:36:55 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented
Oct 18, 2021 1:37:24 AM CDT	Oct 18, 2021 1:37:39 AM CDT	Oct 18, 2021 1:37:45 AM CDT	Answer	15168121234	3343611234	00:00:06	Two-Way Call		Bearer capability not implemented



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 1:37:24 AM CDT	Oct 18, 2021 1:37:39 AM CDT	Oct 18, 2021 1:37:45 AM CDT	Originate	15168121234	3343611234	00:00:06	Two-Way Call	1.1.278.7.109.0	Bearer capability not implemented

Internal Error Code: 1.1.128.11.5.0

Total Call Count: 14

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Oct 17, 2021 12:44:32 AM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 17, 2021 12:44:33 AM CDT	Oct 17, 2021 12:44:33 AM CDT	Oct 17, 2021 12:44:33 AM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 2:42:39 PM CDT	Oct 17, 2021 2:42:39 PM CDT	Oct 17, 2021 2:42:39 PM CDT	Answer	9857321234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 17, 2021 3:10:20 PM CDT	Oct 17, 2021 3:10:20 PM CDT	Oct 17, 2021 3:10:20 PM CDT	Answer	3344181234	311	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:41 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:41 PM CDT	Oct 18, 2021 6:08:41 PM CDT	Oct 18, 2021 6:08:41 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:42 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:42 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Oct 18, 2021 6:08:42 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:45 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number
Oct 18, 2021 6:08:45 PM CDT	Oct 18, 2021 6:08:46 PM CDT	Oct 18, 2021 6:08:46 PM CDT	Answer	3197751234	611	00:00:00	Two-Way Call	1.1.128.11.5.0	Unallocated (unassigned) number

Internal Error Code: 1.1.129.7.66.0

Total Call Count: 13
----------------------

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 15, 2021 11:34:23 AM CDT	Oct 15, 2021 11:34:39 AM CDT	Oct 15, 2021 11:34:40 AM CDT	Answer	5185851234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 15, 2021 11:34:23 AM CDT	Oct 15, 2021 11:34:39 AM CDT	Oct 15, 2021 11:34:40 AM CDT	Originate	+15185851234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error





H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 15, 2021 1:20:14 PM CDT	Oct 15, 2021 1:20:29 PM CDT	Oct 15, 2021 1:20:31 PM CDT	Answer	5189141234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 15, 2021 1:20:14 PM CDT	Oct 15, 2021 1:20:29 PM CDT	Oct 15, 2021 1:20:31 PM CDT	Originate	+15189141234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 17, 2021 8:06:11 AM CDT	Oct 17, 2021 8:06:18 AM CDT	Oct 17, 2021 8:06:19 AM CDT	Answer	5185861234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 17, 2021 8:06:11 AM CDT	Oct 17, 2021 8:06:18 AM CDT	Oct 17, 2021 8:06:19 AM CDT	Originate	+15185861234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 17, 2021 12:25:21 PM CDT	Oct 17, 2021 12:25:23 PM CDT	Oct 17, 2021 12:25:25 PM CDT	Answer	+18509681234	+18006431234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 17, 2021 12:25:21 PM CDT	Oct 17, 2021 12:25:23 PM CDT	Oct 17, 2021 12:25:25 PM CDT	Originate	8509681234	8006431234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 12:54:35 PM CDT	Oct 17, 2021 12:54:51 PM CDT	Oct 17, 2021 12:54:52 PM CDT	Answer	5182321234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 17, 2021 12:54:35 PM CDT	Oct 17, 2021 12:54:51 PM CDT	Oct 17, 2021 12:54:52 PM CDT	Originate	+15182321234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 17, 2021 1:59:54 PM CDT	Oct 17, 2021 1:59:56 PM CDT	Oct 17, 2021 1:59:58 PM CDT	Answer	5185861234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 17, 2021 1:59:54 PM CDT	Oct 17, 2021 1:59:56 PM CDT	Oct 17, 2021 1:59:58 PM CDT	Originate	+15185861234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 17, 2021 2:33:22 PM CDT	Oct 17, 2021 2:33:38 PM CDT	Oct 17, 2021 2:33:39 PM CDT	Answer	5189421234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 17, 2021 2:33:22 PM CDT	Oct 17, 2021 2:33:38 PM CDT	Oct 17, 2021 2:33:39 PM CDT	Originate	+15189421234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error





H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 11:16:34 AM CDT	Oct 18, 2021 11:16:49 AM CDT	Oct 18, 2021 11:16:51 AM CDT	Answer	8023491234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 18, 2021 11:16:34 AM CDT	Oct 18, 2021 11:16:49 AM CDT	Oct 18, 2021 11:16:51 AM CDT	Originate	+18023491234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 18, 2021 11:54:29 AM CDT	Oct 18, 2021 11:54:44 AM CDT	Oct 18, 2021 11:54:46 AM CDT	Answer	8034991234	8034811234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 18, 2021 11:54:29 AM CDT	Oct 18, 2021 11:54:44 AM CDT	Oct 18, 2021 11:54:46 AM CDT	Originate	+18034991234	8034811234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 18, 2021 1:59:49 PM CDT	Oct 18, 2021 2:00:04 PM CDT	Oct 18, 2021 2:00:06 PM CDT	Answer	5183211234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 18, 2021 1:59:49 PM CDT	Oct 18, 2021 2:00:04 PM CDT	Oct 18, 2021 2:00:06 PM CDT	Originate	+15183211234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 6:25:03 PM CDT	Oct 18, 2021 6:25:06 PM CDT	Oct 18, 2021 6:25:08 PM CDT	Answer	5185861234	5185851234	00:00:02	Two-Way Call	1.1.129.7.66.0	Call having the requested call identity has been cleared
Oct 18, 2021 6:25:03 PM CDT	Oct 18, 2021 6:25:06 PM CDT	Oct 18, 2021 6:25:08 PM CDT	Originate	+15185861234	5185851234	00:00:02	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error

Internal Error Code: 1.1.129.7.67.0

Total Call Count: 2
---------------------

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 12:30:24 PM CDT	Oct 17, 2021 12:30:25 PM CDT	Oct 17, 2021 12:30:56 PM CDT	Answer	6016301234	6016381234	00:00:32	Two-Way Call		Internetworking, unspecified
Oct 17, 2021 12:30:24 PM CDT	Oct 17, 2021 12:30:25 PM CDT	Oct 17, 2021 12:30:56 PM CDT	Originate	+16016301234	6016381234	00:00:32	Two-Way Call	1.1.129.7.67.0	Internetworking, unspecified
Oct 17, 2021 3:18:57 PM CDT	Oct 17, 2021 3:19:06 PM CDT	Oct 17, 2021 3:19:08 PM CDT	Answer	+18509681234	+18445831234	00:00:02	Two-Way Call	1.1.129.7.67.0	Internetworking, unspecified



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 17, 2021 3:18:57 PM CDT	Oct 17, 2021 3:19:06 PM CDT	Oct 17, 2021 3:19:08 PM CDT	Originate	8509681234	8445831234	00:00:02	Two-Way Call		Internetworking, unspecified

Internal Error Code: 1.1.185.7.8.0

Total Call Count: 2
---------------------

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 16, 2021 8:31:54 AM CDT	Oct 16, 2021 8:31:55 AM CDT	Oct 16, 2021 8:57:26 AM CDT	Answer	2106061234	3344181234	00:25:31	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 16, 2021 8:31:54 AM CDT	Oct 16, 2021 8:31:55 AM CDT	Oct 16, 2021 8:57:26 AM CDT	Originate	+12106061234	3344181234	00:25:31	Two-Way Call	1.1.185.7.8.0	Call terminated when timer expired, a recovery routine executed to recover from the error



H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 8:41:19 PM CDT	Oct 18, 2021 8:41:34 PM CDT	Oct 18, 2021 9:10:06 PM CDT	Answer	2534801234	2533721234	00:28:32	Two-Way Call		Call terminated when timer expired, a recovery routine executed to recover from the error
Oct 18, 2021 8:41:19 PM CDT	Oct 18, 2021 8:41:34 PM CDT	Oct 18, 2021 9:10:06 PM CDT	Originate	+12534801234	2533721234	00:28:32	Two-Way Call	1.1.186.7.8.0	Call terminated when timer expired, a recovery routine executed to recover from the error

Internal Error Code: 1.1.186.7.7.5

Total Call Count: 1

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 7:25:10 PM CDT	Oct 18, 2021 7:25:20 PM CDT	Oct 18, 2021 7:25:20 PM CDT	Answer	+16016381234	+16018681234	00:00:00	Two-Way Call	1.1.186.7.7.5	Network out of order
Oct 18, 2021 7:25:10 PM CDT	Oct 18, 2021 7:25:20 PM CDT	Oct 18, 2021 7:25:20 PM CDT	Originate	6016381234	6018681234	00:00:00	Two-Way Call		Network out of order



Internal Error Code: 1.1.96.7.25.0

Total Call Count: 1

### Call Details

H323 Setup Time	H323 Connect Time	H323 Disconnect Time	H323 Call Origin	CLID	DNIS	Call Duration (hh:mm:ss)	Voice Feature	Internal Error Code	Disconnect Text
Oct 18, 2021 10:31:07 AM CDT	Oct 18, 2021 10:31:22 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Originate	+18447331234	8592861234	00:00:45	Two-Way Call		Mandatory information element is missing
Oct 18, 2021 10:31:07 AM CDT	Oct 18, 2021 10:31:23 AM CDT	Oct 18, 2021 10:32:07 AM CDT	Answer	8447331234	8592861234	00:00:45	Two-Way Call	1.1.96.7.25.0	Call having the requested call identity has been cleared